Tuesday, 4/25/2006 8:36:52 AM Date: j_i. User: Kim Johnston **Process Sheet** : ARMOR SHIELD : CU-DAR001 Dart Helicopters Services **Drawing Name** Customer Job Number : 26819 : 12369 Estimate Number : D412664203A Part Number : NIA P.O. Number : DSI9326 S.O. No. : NA : 4/25/2006 **Drawing Number** This Issue : NC Project Number : N/A Prsht Rev. : NIA : LANDING GEAR : A **Drawing Revision** Type First Issue : NA : 26812 Material Previous Run : 5/8/2006 Each Qty: 1 Um: **Due Date** Written By Checked & Approved By Comment **Additional Product** Job Number: Description: **Machine Or Operation:** Seq. #: DOCUMENT CONTROL DC 1.0 Comment: Photocopy bluefile & type labels per PPPD412-664-203A CHG001 45.0 Add DSI 9326 to existing paper work. Crosstube Aft High D412664203 2.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) 0 PC 06 06 06 Fwd Crosstube Batch: <u>1325652</u> HAND FINISHING RESOURCE #1 3.0 HAND FINISHING1 Comment: HAND FINISHING RESOURCE #1 1-Remove tube from packaging 2-Apply Armor sheild as per DSI 9326 Batch: 1 1838 A/R Armor Sheild INSPECT POWDER COAT/CHEMICAL CONVERSION 4.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION PACKAGING 1 PACKAGING RESOURCE #1 5.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-664-203A Location:_ 06/06/12 PPP Rev:

Dart Ae	rospace L	.td							
W/O:			WC	ORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			·						
Part No		PAR #:	Fault Cate	gory: N			•	<u>〉</u> Date: <u>△</u> _ Date: _	
NCR:		,	WORK ORDI	ER NON-CONFORMANO				Date	
DATE	OTED	Description of NC		Corrective Action Section B Verificat	ation	Approval Approv			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	Approval QC Inspector

NOTE: Date & initial all entries

Date:

Tuesday, 4/25/2006 8:36:52 AM

User:

Kim Johnston

Customer: CU-DAR001 Dart Helicopters Services

Process Sheet

Drawing Name: ARMOR SHIELD

Job Number: 26819

Part Number: D412664203A

Job Number:



Seq. #:

Machine Or Operation:

Inspection Level 21

Description:

6.0

DC

DOCUMENT CONTROL

Comment: DOCUMENT CONTROL

....

Job Completion



W06.06.13

Dart Aerospace Ltd

	. oopuoo .	- tvi							
W/O:			WC	RK ORDER CHANG	ES		• • • • • • • • • • • • • • • • • • • •		
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									;
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date:	
					QA: N	I/C Close	d:	Date:	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	R)			
D.4.T.F.	0750	Description of NC		Corrective Action Section		Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti		Chief Eng	QC Inspector
							· · ·		

NOTE: Date & initial all entries



DESIG	PH	DRAWN BY		OSPACE LTD ONTARIO, CANADA
CHEC	(ED	APPROVED	DRAWING NO.	REV. A
	$\mathcal{N} \cdot \mathcal{N}$	#	DSI 9326	SHEET 1 OF 1
DATE			TITLE	SCALE
06.0	2.14		ARMOR SHIELD	NTS
Α		06.02.14	NEW ISSUE	

DART SERVICE INSTRUCTION

To further protect Dart crosstubes from mechanical damage in service, they may be treated with "Armor Shield" surface treatment.

INSTALLATION	CANADIAN STC	FAA STC
D205-596-101/-103/-105/-107	SH03-6	SR01742NY
D212-664-101/-201 D412-664-203	SH01-9	SR01298NY
D206-667-101/-103/-201/-203 D407-667-105/-205	SH01-5	SR01304NY
D058-676-101/-201	N/A	SR01018SE

To designate crosstubes with 'Armor Shield' add 'A" to the Part Number. For example, D206-667-101A is a D206-667-101 crosstube coated with Armor Shield. It is acceptable to apply the Armor Shield in regions shown in Figure 1 only. It is NOT acceptable to apply Armor Shield in the cuff and support/clamp regions.

1.0 To apply Armor Shield

- Ensure the crosstube is appropriately finished in accordance with the relevant 1) manufacturing drawing or Instruction for Continued Airworthiness (ICA).
- Mask areas around supports and cuffs per Figure 1. Abrade paint finish in areas 2) requiring protection using 320 grit sandpaper.
- Clean/degrease surface of crosstube using Methyl Ethyl Ketone (MEK), 4105S 3) Wash'n'Wipe Degreaser, or equivalent and wipe the surface to clean the entire area
- Apply 3 coats of Proform PF 746 or PF 746-1 to surface 4)
- (apply additional coats when surface is dry, but not fully cured)
- Allow 5 hours for coating to dry. 5)
- Apply 2 coats of Imron 500s Polyurethane Enamel clear + Dupont Imron 6) Polyurethane Enamel Activator 192S (mix 3:1). Mix 15 minutes prior to application and allow 15 minutes before applying additional coats.

Armor Shield removal/re-application 2.0

To remove the Armor Shield coating or if damage to the coating and/or crosstube is observed during inspection.

- Remove Armor Shield from the affected area using 80 grit sandpaper. To remove 1) Armor Shield from larger areas, bead blasting has been determined to be the most
- effective technique.

 Repair mechanical damage (within limits) to the crosstube and touch up finish in UNCONTROLLED COPY 2)

Apply Armor Shield in accordance with Section 1.0 of these instructions. 3)

SHOP COPY RETURN TO

SUBJECT TO AMENDMENT

WITHOUT NOTICE WORK ORDER NO. 26819


CANADA DEPARTMENT OF TRANSPORT

AIRCRAFT CERTIFICATION **BRANCH** DAO # 01-O-01

APPROVED BY:

D. SHEPHERD (DE # 02)

DATE: 06.02.14 SH03-6/SH01-9/SH01-5 CERT. NO.: ISSUE NO .: 3/3/3



ACCEPTABLE REGIONS TO BE COATED WITH ARMOR SHIELD FIGURE_1

Copyright © 2006 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.